

FIG. 1A




FIG. 1B

4,003,934-5 • 1,023,01




FIG. 2




FIG. 3

10039845 102301




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A





FIG. 6B

6/25

FIG. 6C



7/25

FIG. 7A




FIG. 7B





FIG. 7C



432301-503600-0001

8/25

FIG. 3A

EFFECT ON PULSE RATE


RIGHT ATRIUM MUSCLE



TOEOT "545600"

9/25

FIG. 8B



10/25

FIG. 9






FIG. 10




12/25

FIG. 11



13/25

Flow (ml/min)



Aortic Pressure (mmHg)




FIG. 12

14/25




FIG. 13

410039845.1022301

FIG. 14





FIG. 15



17/25

FIG. 16




FIG. 17




FIG. 18A




FIG. 18B




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23

